

COPY

Elks Lodge Asbestos Survey

To: Billy Thomas

Elks Lodge Building

Administration Area, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
Cove Base, White	None	Rhoades	5/4/2001						

Auditorium, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
Acoustical Ceiling Mat	chrysotile	Rhoades	5/4/2001						
Cove Base Mastic, Dark Brown	None	Rhoades	5/4/2000						

Ballroom Area, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
Acoustical Ceiling Mat	chrysotile	Rhoades	5/4/2001						

Ballroom&Dining Area, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
Black Wood Flooring Mastic	None	Rhoades	5/4/2001						

Bathhouse, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>

Paint Surface

<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
White		2/17/2003	Good			

Bathroom, Department

<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Beige		5/4/2001				

Concessions, Department

<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
White		2/17/2003	Good			

Dinning Room, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
12"x12" Floor Tile, Brown	None	Rhoades	5/4/2001						
Floor Tile Mastic, Tan	None	Rhoades	5/4/2001						

E.face of bldg., Department

Elks Lodge

Elks Lodge Building

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
CMU Wall	Tan		2/17/2003				

Entrance Flag Pole Stand, Department

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Paint	Cream		5/4/2001		100		

Entryway & Loung, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
Acoustical Ceiling Mat	chrysotile	Rhoades	5/4/2001						

Entryway Area, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
9"x 9" Floor Tile, Brown	chrysotile	Rhoades	5/4/2001						
9"x 9" Floor Tile, White	chrysotile	Rhoades	5/4/2001						
Floor Tile Mastic, Black	chrysotile	Rhoades	5/4/2001						

Exterior Block Wall, Department

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Paint	Beige		5/4/2001		100		

Exterior Gutters, Department

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Paint	White		5/4/2001		100		

Exterior Parking Area, Department

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Paint	Yellow		5/4/2001		22570		
Paint	Red		5/4/2001		7870		
Paint	Blue		5/4/2001		22160		
Paint	Aqua Blue		5/4/2001		18520		

Exterior Trim&Gutters, Department

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Paint	Brown		5/4/2001		990		

Gym Addition, Department

Elks Lodge

Elks Lodge Building

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
2'x4' Ceiling Tile	chrysotile	Rhoades	5/4/2001						
9"x 9" Floor Tile, Brown	chrysotile	Rhoades	5/4/2001						
9"x 9" Floor Tile, White	chrysotile	Rhoades	5/4/2001						
Cove Base - Beige	None	Rhoades	5/4/2001						
Cove Base Mastic, Brown	chrysotile	Rhoades	5/4/2001						
Cove Base, White	None	Rhoades	5/4/2001						
Floor Tile Mastic, Black	None	Rhoades	5/4/2001						
Roofing Paper, Gray	chrysotile	Rhoades	5/4/2001						
Roofing Tar, Black	chrysotile	Rhoades	5/4/2001						
Sound Board Material	None	Rhoades	5/4/2001						
TSI Fitting Insulation	chrysotile	Rhoades	5/4/2001						

Interior Walls&Trim, Department

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Paint	White		5/4/2001		1050		
Paint	Beige		5/4/2001		100		

Kitchen, Department

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Paint	Blue		5/4/2001		140		

Large Lounge Area, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
12"x12" Floor Tile, Brown	chrysotile	Rhoades	5/4/2001						
9"x 9" Floor Tile, Green	chrysotile	Rhoades	5/4/2001						
Acoustical Ceiling Mat	chrysotile	Rhoades	5/4/2001						
Cove Base - Beige	None	Rhoades	5/4/2001						
Floor Tile Mastic, Black	None	Rhoades	5/4/2001						
Floor Tile Mastic, Tan	None	Rhoades	5/4/2001						

Locker Room, Department

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Paint	White		2/17/2003	Good			

Mechanical Room, Department

Elks Lodge

Elks Lodge Building

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
2" Heat Exchanger Fittings	chrysotile	Rhoades	5/4/2001						
6" Heat Exchanger Fittings	chrysotile	Rhoades	5/4/2001						
Hot Water Tank Insulation	chrysotile	Rhoades	5/4/2001						
Mechanical Equipment Gaskets	chrysotile	Rhoades	5/4/2001						

Meeting Rooms, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
Cove Base Mastic, Beige	None	Rhoades	5/4/2001						
Cove Base Mastic, Light Brown	None	Rhoades	5/4/2001						

Membrane Roof Area, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
Gray Roofing Tar	chrysotile	Rhoades	5/4/2001						
Roofing Tar, Black	chrysotile	Rhoades	5/4/2001						

Old Kitchen-15N-2E SW Crnr Clg, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
		ATC	7/1/2004				9 sq ft		O & M
Gray Gypsum Wallboard System	None	ATC	6/11/2004	Good		Non-	1800 sq ft.		

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Paint	Gray		6/11/2004	Good	0.113		

Old Kitchen-16N-3E SW Cnr Clng, Department

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Paint	Gray		6/11/2004	Good			0.113% lead

Old Kitchen-17N-4E SW Cnr Clng, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
Gray Gypsum Wallboard System	None	ATC	6/11/2004	Good		Non-	1800 sq ft.		

Old Kitchen-19N-2E SW Cnr Clng, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
Gray Gypsum Wallboard System	None	ATC	6/11/2004	Good		Non-	1800 sq ft.		

Original Roof Area, Department

Elks Lodge

Elks Lodge Building

<u>Asbestos Material</u>	<u>Asbestos Type</u>	<u>Inspector</u>	<u>Last Inspected</u>	<u>Condition</u>	<u>Accessibility</u>	<u>Friability</u>	<u>Quantity</u>	<u>Exposure#</u>	<u>Recommend</u>
Parapet Tar, Silver	None	Rhoades	5/4/2001						
Roofing Paper, Gray	None	Rhoades	5/4/2001						
Roofing Tar, Black	chrysotile	Rhoades	5/4/2001						
Roofing Tar, Black - Patching	chrysotile	Rhoades	5/4/2001						

Pool Building, Department

<u>Asbestos Material</u>	<u>Asbestos Type</u>	<u>Inspector</u>	<u>Last Inspected</u>	<u>Condition</u>	<u>Accessibility</u>	<u>Friability</u>	<u>Quantity</u>	<u>Exposure#</u>	<u>Recommend</u>
TSI Fitting Insulation	chrysotile	Rhoades	5/4/2001						

<u>Paint Surface</u>	<u>Color</u>	<u>Inspector</u>	<u>Last Inspected</u>	<u>Condition</u>	<u>Pb (ppm)</u>	<u>TCLP</u>	<u>Quantity</u>
Paint	Yellow		5/4/2001		100		
Paint	Beige		5/4/2001		100		
TSI Paint Covering	Beige		5/4/2001		870		

Roof, Department

<u>Asbestos Material</u>	<u>Asbestos Type</u>	<u>Inspector</u>	<u>Last Inspected</u>	<u>Condition</u>	<u>Accessibility</u>	<u>Friability</u>	<u>Quantity</u>	<u>Exposure#</u>	<u>Recommend</u>
Roofing Felt Fibrous	None	Shisman & Asso	2/17/2003	damaged		Non-			
Sealant Plastic	chrysotile	Shisman & Asso	2/17/2003	Fair		Non-			

Roof Area, Department

<u>Asbestos Material</u>	<u>Asbestos Type</u>	<u>Inspector</u>	<u>Last Inspected</u>	<u>Condition</u>	<u>Accessibility</u>	<u>Friability</u>	<u>Quantity</u>	<u>Exposure#</u>	<u>Recommend</u>
HVAC Duct Mastic, Red	chrysotile	Rhoades	5/4/2001						
HVAC Flex Connector	None	Rhoades	5/4/2001						

S.side of bldg., Department

<u>Paint Surface</u>	<u>Color</u>	<u>Inspector</u>	<u>Last Inspected</u>	<u>Condition</u>	<u>Pb (ppm)</u>	<u>TCLP</u>	<u>Quantity</u>
Door Frame	blue/green		2/17/2003				

Scalloped Ceiling Areas, Department

<u>Asbestos Material</u>	<u>Asbestos Type</u>	<u>Inspector</u>	<u>Last Inspected</u>	<u>Condition</u>	<u>Accessibility</u>	<u>Friability</u>	<u>Quantity</u>	<u>Exposure#</u>	<u>Recommend</u>
Acoustical Ceiling Mat	chrysotile	Rhoades	5/4/2001						

Shower, Department

<u>Asbestos Material</u>	<u>Asbestos Type</u>	<u>Inspector</u>	<u>Last Inspected</u>	<u>Condition</u>	<u>Accessibility</u>	<u>Friability</u>	<u>Quantity</u>	<u>Exposure#</u>	<u>Recommend</u>
Insulation elbow, domestic water piping	chrysotile	Shisman & Asso	2/17/2003	damaged					

Sm. Meeting Rooms, Department

<u>Asbestos Material</u>	<u>Asbestos Type</u>	<u>Inspector</u>	<u>Last Inspected</u>	<u>Condition</u>	<u>Accessibility</u>	<u>Friability</u>	<u>Quantity</u>	<u>Exposure#</u>	<u>Recommend</u>
Acoustical Ceiling Mat	chrysotile	Rhoades	5/4/2001						

Elks Lodge

Elks Lodge Building

Small Bar Area, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
12"x12" Floor Tile, Orange	chrysotile	Rhoades	5/4/2001						
12"x12" Floor Tile, Wood-like	chrysotile	Rhoades	5/4/2001						
9"x 9" Floor Tile, Beige	chrysotile	Rhoades	5/4/2001						
Floor Tile Mastic, Black	chrysotile	Rhoades	5/4/2001						
Floor Tile Mastic, Tan	None	Rhoades	5/4/2001						

Storage Room, Department

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Paint	Yellow		5/4/2001		100		
Paint	Green		5/4/2001		100		
Paint	Cream		5/4/2001		100		

Surplus & Recycling/Rm.121, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
White Dust from HVAC	None	dye	5/12/2003	Good	High				

Throughout, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
12"x12" Ceiling Tile, Mastic	None	Rhoades	5/4/2001						
Carpet Mastic	None	Rhoades	5/4/2001						
Exterior Stucco	None	Rhoades	5/4/2001						
Floor Leveling, Compound, White	None	Rhoades	5/4/2001						
Interior Plaster	None	Rhoades	5/4/2001						
Interior Sheetrock	None	Rhoades	5/4/2001						

Under Carpet near Lounge, Department

<i>Asbestos Material</i>	<i>Asbestos Type</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Accessibility</i>	<i>Friability</i>	<i>Quantity</i>	<i>Exposure#</i>	<i>Recommend</i>
9"x 9" Floor Tile, Lime Green	None	Rhoades	5/4/2001						

W.Side of bldg., Department

<i>Paint Surface</i>	<i>Color</i>	<i>Inspector</i>	<i>Last Inspected</i>	<i>Condition</i>	<i>Pb (ppm)</i>	<i>TCLP</i>	<i>Quantity</i>
Beam, steel	Blue		2/17/2003				